

**TOOLMASTER**



**3MT x JT3 Drill Chuck Arbor**

**Suits Ø16mm Drill Chucks**



## TOOLMASTER 3MT x JT3 Drill Chuck Arbor

### Description

Drill chuck arbors have one end which is the taper of the machine. The most common are Morse Tapers for mounting in a drill press spindle or lathe, or NT tapers for mounting in milling machines. The other end of the arbor is a short taper called a Jacobs Taper that is driven into the taper in the chuck body. The JT taper or Jacobs Taper is the most commonly used taper for mounting a drill chuck. The most common tapers used in Australia are JT2, JT3, JT4 & JT6

### Features

- Precision ground and tanged

### Specifications

<b>ORDER CODE</b>	D443A
<b>Long Taper (MT)</b>	3MT
<b>Short Taper (JT)</b>	JT3
<b>Suits Chuck Size (mm)</b>	16
<b>Threaded Shank</b>	~